

Fisherman's Table – Internal Guttering

Project: Incorrect Guttering Fitments

Before...

Category: Water Seepage

Completion

Date: October 2005

System: Rhino Linings TUFF STUFF



Job Description

This guttering system had been designed incorrectly with water running away from drainage points and pooling where it shouldn't. This left water to seep into the building. The gutters were reformed and the flow adjusted then coated with TUFF STUFF to eliminate the incorrect flow.

After...

