

Energy Sub Station Bund

Project: Integral Energy Substation

Category: Secondary Containment

Completion

Date: August 2006

Product: Rhino Linings Tuff Stuff



Job Description

Four transformers at the Integral Energy Sub Station were experiencing oil containment problems. The transformers were leaking oil onto and through the concrete, leaching into the ground below.

After having the concrete cleaned, and the brick walls bagged, Rhino Linings Duraspray was applied to the walls and floors to form a fully contained bed area. 24 grit aggregate was also added to the traffic areas addressing OH&S requirements.

The Sub Station management and staff were pleased with the result, their problem solved.



Before



After

