

Before...

Water Tank

Project: Tank

Category:

Completion

Date: December 2004

System: Rhino Linings TUFF STUFF



Job Description

This 40 metre long tank was suspended 3 meters above a workshop floor containing various electronic machinery and motors. Major problems occurred due to the tank leaking water onto the motors below causing them to blow up, this would shut the whole plant down until the motors were repaired..

Both the walls and floor of the tank were lined with TUFF STUFF. It was then water tested and had no leaks.



After...

